



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:19PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 001
Comments: View of
concrete, soil,
asphalt and rock
pile area.



Date:09-04-2014
Time: 12:19PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 002
Comments: View of
concrete, soil,
asphalt and rock
pile area.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:20PM
Direction: Southwest
Photo by: Jen O'Hearn
Exposure #: 003
Comments: View of concrete, soil, asphalt and rock pile area.



Date:09-04-2014
Time: 12:21PM
Direction: Northeast
Photo by: Jen O'Hearn
Exposure #: 004
Comments: View of soil, rock, asphalt and landscape waste.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:31PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 005
Comments: View of
corrugated metal
pipe and
dimensional
lumber.



Date:09-04-2014
Time: 12:32PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 006
Comments: View of
corrugated metal
pipe in with a soil,
rock, asphalt pile
covered with
weeds.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:33PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 007
Comments: View of a
broken fiberglass
and metal ladder.



Date:09-04-2014
Time: 12:36PM
Direction: Southeast
Photo by: Jen
O'Hearn
Exposure #: 008
Comments: View of
brick in pile with
soil and rock with
weeds growing.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:40PM
Direction: Southeast
Photo by: Jen
O'Hearn
Exposure #: 009
Comments: View of
brick and concrete
in with soil pile.



Date:09-04-2014
Time: 12:41PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 010
Comments: View of
concrete in with
soil pile with
weeds growing.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:42PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 011
Comments: View of
water and piles
along the edge of
excavation.



Date:09-04-2014
Time: 12:42PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 012
Comments: View of
low lying area and
concrete pile on
edge of
excavation.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:45PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 013
Comments: View of
one apparent
painted curb piece
of concrete and
concrete pieces in
the weeds.



Date:09-04-2014
Time: 12:45PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 014
Comments: View of
concrete and brick
and soil piled up in
the weeds.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:45PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 015
Comments: View
along edge of
excavation.



Date:09-04-2014
Time: 12:48PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 016
Comments: View of
brick and asphalt
on slope of
excavation.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:48PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 017
Comments: View of
low lying area with
vegetation.



Date:09-04-2014
Time: 12:50PM
Direction: Northeast
Photo by: Jen
O'Hearn
Exposure #: 018
Comments: View of
metal pipe looking
up slope of
excavation.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:51PM
Direction: Northeast
Photo by: Jen
O'Hearn
Exposure #: 019
Comments: View of
large chunk of
asphalt looking up
slope of
excavation.



Date:09-04-2014
Time: 12:51PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 020
Comments: View of
low-lying area's
vegetation.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 12:56PM
Direction: North
Photo by: Jen O'Hearn
Exposure #: 021
Comments: View of asphalt and concrete curb.



Date:09-04-2014
Time: 12:59PM
Direction: North
Photo by: Jen O'Hearn
Exposure #: 022
Comments: View of more piles of concrete and soil with weeds.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 1:01PM
Direction: Southwest
Photo by: Jen
O'Hearn
Exposure #: 023
Comments: View of
surveyor's stake
and concrete in
soil pile.



Date:09-04-2014
Time: 1:02PM
Direction: Northeast
Photo by: Jen
O'Hearn
Exposure #: 024
Comments: View
across site back
towards the
entrance.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
Time: 1:06PM
Direction: Southeast
Photo by: Jen
O'Hearn
Exposure #: 025
Comments: View of
partially painted
fence in a pile.



Date:09-04-2014
Time: 1:15PM
Direction: Northwest
Photo by: Jen
O'Hearn
Exposure #: 026
Comments: View of
no dumping sign
and gated
entrance.



DIGITAL PHOTOGRAPHS File Names: 1138175001~09042014-[Exp. #].jpg



Date:09-04-2014
 Time: 1:15PM
 Direction: Northwest
 Photo by: Jen O'Hearn
 Exposure #: 027
 Comments: View of authorized vehicle only beyond this point sign.



Date:09-04-2014
 Time: 1:15PM
 Direction: Northwest
 Photo by: Jen O'Hearn
 Exposure #: 028
 Comments: View of City of Bloomington no trespassing sign on new gate.